Filed 10/6/11

## CERTIFICATE OF SUBSTANTIAL COMPLETION

DATE OF ISSUANCE September 19, 2011		
	75-4	734
OWNER St. Charles Parish		
CONTRACTOR M.R. Pittman Group, LLC		
Contract: East Bank Water Treatment P	lant Upgrade	
Project: East Bank Water Treatment P		
OWNER's Contract No. <u>WWKS-44</u>	ENGINEER's Project No. 89170.1	
This Certificate of Substantial Completion applie specified parts thereof:	es to all Work under the Contract Documents an	d/or to the following
To St. Charles Parish		
	OWNER	
1 Im 11 D Div 0		
And To M.R. Pittman Group, LLC	GOVERN + GROD	
	CONTRACTOR	

The Work to which this Certificate applies has been inspected by authorized representatives of OWNER, CONTRACTOR and ENGINEER, and that Work is hereby declared to be substantially complete in accordance with the Contract Documents on

## September 19, 2011 DATE OF SUBSTANTIAL COMPLETION

A tentative list of items to be completed or corrected is attached hereto. This list may not be all-inclusive, and the failure to include an item in it does not alter the responsibility of CONTRACTOR to complete all the Work in accordance with the Contract Documents. The items in the tentative list shall be completed or corrected by CONTRACTOR within 45 days of the above date of Substantial Completion.

EJCDC No. 1910-8-D (1996 Edition)

Prepared by the Engineers' Joint Contract Documents Committee and endorsed by The Associated General Contractors of America and the Construction Specifications Institute.

The responsibilities between OWNER and CONTRACTOR for security, operation, safety, maintenance, insurance and warranties and guarantees shall be as follows:

OWNER: St. Charles Parish will assume insurance upon final payment. No warranties or guarantees will be assumed by St. Charles Parish until the one-year warranty/guarantee period has ended, in full accordance with Article 13.12 of Section 00700 of the East Bank Water Treatment Plant Upgrade Contract Documents.

CONTRACTOR: Contractor shall remain responsible for secur	rity of equipment and materials, safety,
and maintenance during completion of punchlist items. Contr	•
guarantees for a period of one year after the substantial completi	ion date, in full accordance with Article
13.12 of Section 00700 of the East Bank Water Treatment Plant U	-
The following documents are attached to and made a part of this (	Certificate:
Substantial Completion Punchlist for East Bank Water Treatment	Plant Upgrade
This certificate does not constitute an acceptance of Work not in a Documents nor is it a release of CONTRACTOR's obligation to cothe Contract Documents.	accordance with the Contract omplete the Work in accordance with
Executed by ENGINEER on SEPT. 19 , 2011	
Shread-Kuyrkendall & Associates, Inc.  ENGINEER  By: (David A. Einsel, P.E.)	· · · · · · · · · · · · · · · · · · ·
CONTRACTOR accepts this Certificate of Substantial Completion  M.R. Pittman Group, LLC  CONTRACTOR  By:  (Michael R. Pittman, P.E., Hesident)	n on
OWNER accepts this Certificate of Substantial Completion on  St. Charles Parish	Oct. 6, 2011
(V.J. St. Pierre, Ir., Parish President)	RECORDED IN THE ST. CHARLES PARISH CLERK OF COURT OFFICE ON 10/6/11
	AS ENTRY NO. 373609  IN MORTGAGE CONVEYANCE BOOK NO. 1445 FOLIO 212

<del></del>			7		7	·	<del>,</del>	<del></del>
lte	n						Balance	Balance
No		Location	Floor	Comments	Status	Original \$	9/7/11	9/15/11
		<u> </u>	<del>                                     </del>		1	Chighnary	1 3/1/11	3/13/11
1	North door in Bunk Room needs adjusting	Control Building	2	Review for specifics	,	\$100	\$100	\$100
2	All floors and walls need cleaning	Control Building	All	In progress	75%	\$1,200	\$400	\$400
	All exterior doors have gaps on bottom;							7.00
	some still require adjustement (especially			Thresholds sealed	ł			
3	west door on 2nd floor)	Control Building	All	and sweeps installed	75%	\$200	\$50	\$50
	Shutter over kitchen window needs							
4	touchup paint and roller guides	Control Building	2			\$100	\$100	\$100
5	Exterior door on 3rd Floor Storage Room	Canita I Destit	١.,			4		
-	has a gap	Control Building	3.	See Item No. 8 Combine with Item	75%	\$50	\$50	\$50
6	General cleaning of entire plant			No. 29	75%	¢1 E00	¢1.000	¢1.000
	Clean and repaint stairs and stairwells in			110. 23	73/6	\$1,500	\$1,000	\$1,000
7	plant	Control Building	All	in progress	50%	\$300	\$150	\$150
8	Need guards around AC units	Yard		G	3070	\$400	\$400	\$400
							7.00	7,00
	Sink counter top has seam too close to sink			No criteria specified				l
9	to be discussed with SCP	Control Building	2	for seam locations		\$1,500	\$1,500	\$1,500
į								
		Caratural Dividian -/						
10	Complete FRP handrails	Control Building/ Clarifiers/ Filters	AL/A	Moiting an delice.	500/	¢50.000	454.555	
10	· ·	Claimers/ Filters	N/A	Waiting on delivery	50%	\$50,000	\$21,000	\$21,000
		Control Building/			1			
	Clean the bottom of the walls for both the	Chemical Feed		Control Building				
11	Control and Chemical Feed Buildings	Building	1	complete	75%	\$3,000	\$1,500	\$800
12	Site dressup, cleanup, grading, & seeding	Yard	N/A		50%	\$3,000	\$3,000	\$1,500
1					1	İ		
		Control Building/ Chemical Feed		·	İ	ĺ		
13	Touch-up painting	Building/Yard	N/A	Review for specifics	750/	¢5.000	¢4.500	44 500
	Additional patching and paving - to be	Danang/ raru	N/A	Review for specifics	75%	\$5,000	\$1,500	\$1,500
14	discussed with SCP	Yard	N/A	Paving complete	l	\$10,000	\$5,000	\$5,000
	Correct vinyl wall sheet splice trim and			8		ψο,000	73,000	\$5,000
15	molding	Control Building	Ali	Review for specifics		\$2,000	\$2,000	\$2,000
	Grade between Chemical Feed Building and							
	clearwells; Consult with SCP to determine							
10	whether grass or limestone will be added						1	1
16	to this area Clean wall walls, floors, junction boxes, etc.	Yard		Complete	75%			
17	in electrical chase room	Control Building	- 1	Part of general		]		. ]
<del> '-</del>	crossreal chase room	COLUDI DUIIOLIS	All [	cleanup				
	Ensure all doors have screws in hinges;	Control Building/	1			.		
l	South door out of Control Room still needs	Chemical Feed			1			
18	three screws on bottom hinge	Building	All (	Complete	95%			
		Chemical Feed		•				
19	Adjust door closure in ammonia room	Building	N/A					1
		0						
20		Control Building/	,,,				1	
	Clean glue and dirt in shower and walls in	Filters/ Clarifiers	Ali					
	bathroom; Caulking/glue still present on	j	l r	Part of general			[	
21		Control Building		-	75%			•
=		Control Dulluling	٢ ار	acutup .	1370			

<u></u>					·	<del></del>	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·
-	Check fridge water dispenser - water							
	dispenser does not shut off upon removal							
22		Control Building	2					
1	Add floor-mount door stops to							
1	Computer/Storage Room 207, Office 201			·				
23		Control Building						
24		Control Building	3					
	Need weather stripping on outside door at	-						
25		Control Building	2	7				
26	Caulk bottom of rollup door at west end	Control Building	1					
	1	Stairs and						
	Galvanize rust spots and tighten any loose	Landings -						
27		Control Building	N/A					
1	North outside door in stairwell has a							
	crack/gap above and below the lock that							
	requires additional weatherstripping or							
28	lock adjustment	Control Building	1					
	Kick plates on door of north 3rd Floor office							
29	need tightening	Control Building	3					
	Check around filters and clarifiers and					·····		
30	repair leaks	Clarifiers/ Filters	N/A					
	Reapir concrete where flaking off outside							
31	walls of clarifiers and filters	Clarifiers/ Filters	N/A					
	Patch holes in filter walls where temporary							
32	walks were located	Filters	N/A		ļ			
	Grind bolt down and grout over in north							
33	wall of north filter on very top	Filters	N/A					
34	Repair cycling vacuum pump on north filter	Filters	N/A		}			Ī
	Sight glass and light globe to be replaced		1				1	[
35	within vacuum tank house on north filter	Filters	N/A		1			. ]
l	Dress up/add fill dirt by Valero fence and		-					
36	where temporary piping removed	Yard	N/A		1			
	Repair leaking rapid mix motors on rapid						<del></del>	
37	mix chambers	Clarifiers	N/A				j	1
	Gear box for PAC tank mixer outside is							
38	rattling and needs adjustment	Yard	N/A				ŀ	
	HVAC equipment in HVAC/ Storage Room							
	301 is rattling badly - may require some				1		į	İ
39	adjustment	Control Building	3					
		- 3						
	Fix low spots in asphalt at the western							į
	rollup door on the Plant Control Building;		]					
40	this spot holds at least an 1" of water	Yard	N/A					
	Remove all excess stockpile fill material			· · · · · · · · · · · · · · · · · · ·			<del></del>	
41	from the back of the plant site	Yard	N/A			İ		1
	Remove all equipment, trailers, etc. from		7.1					
	site and dress up with fill dirt and seeding	į			1		ĺ	-
42	where required	Yard	N/A			ļ		

\$78,350 \$37,750 \$35,550