## **SECTION 00806**

## CHANGE ORDER

DATE OF ISSU	JANCE <u>March 23, 2020</u>	EFFECTIVE DATE	
OWNER	St. Charles Parish		
	R Williams Contractors & Constr	ruction Services, LLC	
Contract:	211 0010 000 000 000 000	THE COLUMN	
-	NA COMMUNITY CENTER ADD	<u>ITION</u>	
OWNER's Contract No. <u>GBKA0219</u> ARCHITECT's Contract No.			
ARCHITECT: 1	MURRAY ARCHITECTS, INC.		

You are directed to make the following changes in the Contract Documents: **Description:** 

- 1. Delete the Following Work Items
  - a. Credit Relocation of Infrastructure.

Delete of \$-10,000.00 (L.S.)

No. One (1)

Total of Deleted Work Items = \$-10,000.00

- 2. Add the Following Work Items:
  - a. Install 2 interior grade beams. See attached Construction Change Directive No. 1 for details.. Addition of \$1,500.00 (L.S.).
  - b. Disconnect and reconnect electrical services, cut 2" discharge line, cut 4" sewer line back approx.. 17', slope to drain away from building, install 2 ft. extension top for sewer lift station. See attached Construction Change Directive No. 2 for details.

Addition of \$ 2,800.00 (L.S).

- c. Additional light in the closet area. See attached Construction Change Directive No. 3 for details. Addition of \$625.00 (L.S.).
- d. Add run-off's for downspouts. See attached Construction Change Directive No. 3 for details. Addition of \$150.00 (L.S.)
- e. Landscaping perimeter of the building. See attached Construction Change Directive No. 3 for details.

Addition of \$2,500.00 (L.S.)

f. Additional flooring attic and wall shelving in attic. See attached Construction Change Directive No. 3 for details.

Addition of \$2,300.00 (L.S.)

Total of Added Work Items = \$9,875.00

3. Revise the Following Work Item Quantities: - Not Applicable

Reason for Change Order: List a reason for each Line Item listed above.

- 1. Deleted Work Items
  - a. Credit Relocation of Infrastructure.
- 2. Add Work Items

- a. Two additional grade beams were required to be added to the foundation when it was discovered that the existing building slab could not be doweled??? due to existing foundation conditions.
- b. Existing sewer line was discovered to be sloping away from the lift station. This change was necessary to correct the issue.
- c. Additiona lights were needed for access to storage materials.
- d. This change was required to ensure downspouts did not wash away newly installed landscape.
- e. As required landscaping bids and plants were installed at perimeter of building.
- f. As requested by the Owner to provide additional flooring in attic for storage space.
- 3. Revise Work Item Quantities Not Applicable

Attachments: (List documents supporting change)

CHANGE IN CONTRACT PRICE:	CHANGE IN CONTRACT TIMES:
Original Contract Price \$224,600.00	Original Contract Times: Substantial Completion: Ready for final payment: (days or dates)
Net Increase (Decrease) from previous Change Orders No to: \$0.00	Net change from previous Change Orders No to No: Substantial Completion: Ready for final payment: (days)
Contract Price prior to this Change Order: \$224,600.00	Contract Times prior to this Change Order: Substantial Completion: Ready for final payment: (days or dates)
Net decrease of this Change Order: \$-125.00	Net increase (decrease) this Change Order: Substantial Completion: Ready for final payment: (days)
Contract Price with all approved Change Orders: \$224,475.00	Contract Times with all approved Change Orders: Substantial Completion: Ready for final payment: (days or dates)
RECOMMENDED:  By:  ARCHITECT(Authorized Signature)  By:  OWNER (Authorized Signature)	By: Clybl Williams
Date: 3-23-2020 Date:	Date: 3-23-2020

2016