CERTIFICATE OF SUBSTANTIAL COMPLETION

DATE OF ISSUANCE	November 21, 2	013				
OWNER <u>St. Charles Parisl</u>						
CONTRACTOR Southern						_
Contract: <u>Courthouse Door</u> Project: <u>St. Charles Paris</u> !			w Replacement			_
1 10 Joot. Dt. Charles 1 mins.	a Com impuse 17001	OTHER TY THESE	AA TECHNOLOGI			_
OWNER's Contract No. <u>H</u>	MGP#1786-089-00	001	ENGINEER	's Project No	N/A	
This Certificate of Substan specified parts thereof:	tial Completion app	lies to all Wo	rk under the Conti	ract Documents o	r to the following	
					•	
					•	
Τ.	C'	T. CHARLES	LOIGH			
То		OWN				
		0 11.21				
And To	SOUTHER	RN CONSTR	UCTION OF ME	TAIRIE, LLC		
		CONTRA	CTOR			
			•			
						_
The Work to which this Ce CONTRACTOR and ENG the Contract Documents on	INEER, and that Wo					th
	D I MIL OL		per 21, 2013		e de la companya de l	
	DATE OF	SUBSTANT	IAL COMPLETION	JN .		
A tentative list of items to be failure to include an item in accordance with the Contra CONTRACTOR within	n it does not alter the act Documents. The	e responsibilit items in the t	y of CONTRACT tentative list shall	OR to complete a	all the Work in	
			•			
		,				
EJCDC No. 1910-8-D (1996 Edi Prepared by the Engineers' Joint Contra	tion) act Documents Committee an	d endorsed by The	Associated General Contr	ractors of America and th	e Construction Specification	s

The responsibilities between OWNER and CONTRACTOR for sheat, utilities, insurance and warranties and guarantees shall be a	
OWNER: HAS FULL USE AND MAINTENANCE RESPONSE	BILITIES OF THE SITE.
CONTRACTOR: to complete or respond to the attached Punch I	ist dated 11/20/13
CONTRACTORS <u>to compasse of respond to the distance of allow</u>	7.51. (44.04 17.20(15)
The following documents are attached to and made a part of this	Certificate:
	Certificate.
Punch List, dated 11/20/13	
This certificate does not constitute an acceptance of Work not in Documents nor is it a release of CONTRACTOR's obligation to of the Contract Documents. Submit 6(six) original documents and contractor to St. Charles Parish Government Building PO Box 302, Hahnville, LA 70057, for processing.	complete the Work in accordance with signed and dated by the engineer
Executed by ENGINEER on November 21, 2013 Date Danny J. Hebert, P.E., LLC ENGINEER By: (Authorized Signature)	
CONTRACTOR accepts this Certificate of Substantial Completic Southern Construction of Metairie, LLC CONTRACTOR By: (Authorized Signature)	Date November 21, 2013
OWNER accepts this Certificate of Substantial Completion on	November 21, 2013 Date RECORDED IN THE ST. CHARLES PARISH CLERK OF COURT OFFICE ON 12/16/13
	AS ENTRY NO. 394205
00808 rev4 Dec 7, 2010	INMORTGAGE/CONVEYANCE BOOK NO. 1558 FOLIO 423

Courthouse Doors and Window Punch List

Project No. HMGP#1786-089-0001

Completed Items

October 31, 2013 (Revised 11-20-13)

- 1. The removal of the tape residue from the entrance door frames at the south east and south west corner entrance.
- 2. Seal all gaps between the window frame and new automatic doors in the north east front entrance and between new curtain walls and precast panels.
- 3. Detail the structural interior sealant on all windows on both floors around all windows next to the frames. (Most windows have problems with the sealant).
- 4. Install the wood trim on the wall-partion dividers in Judge Morel's Office and paint to match existing columns.
- 5. Install the break metal wall partitions on the first floor at the inter walls that occur next to the glass curtain walls. (One in Sherriff's Tax area, two in the Assessor's Office and five in the Finance Office) These need to include sound deadening material as they are installed.
- 6. Install the air condition slot vents next to all glass curtain walls on the first floor.
- 7. Secure all base plywood to interior concrete curb prior to installing the vinyl base.
- 8. Install vinyl base below the curtain walls in all rooms on the first floor.
- 9. Complete the repair and painting of all opening (Gaps) adjacent to the windows on all floors in all rooms. Metal may be used.
- 10. Remove roll off container and glass shipping racks.
- 11. Remove all wood from the rear south east entry.
- 12. Check all thresh holds for proper hole alignment for locking bolts. Threshold at the North West entrance must be changed.
- 13. No interior sealant in one window in the District Attorney's Office.
- 14. One window behind secretarial station in third floor Sherriff's Office is missing sealant and metal trim and sealant.
- 15. Tape glue on window frame in District Attorney's Office and Finance Area.
- 16. Missing break metal on the interior at vertical glass wall connections on the first floor.
- 17. In the Sherriff's Office Area several windows have black marks on the glass.
- 18. All windows need to be cleaned (in and out).
- 19. The entrance light in the soffits shall be replaced with LED Floodlights. ***
- 20. The metal in the entrance soffits shall be replaced with (1/4") powder coated soffit panels. ***
- 21. Keyways and locks shall match the existing system.
- 22. Anchorage schedule must be submitted.
- 23. All warranty information on materials used must be submitted.
- 24. Paint all repaired areas to match existing paint color.
- 25. All doors shall have door stops.
- 26. Install vinyl base as required.
- 27. Complete Judges Area with paint and metal trim.

(***Under Review)