

# Resident's pics: ditches Murray Hill to Belle Ormond – most of these were excavated and cleared in 2020 to 2021


1. Murray Hill Trestle at CN RR looking S
2. Ditch on North side of CN RR between MH trestle & MH East
3. Ditto, showing shoaling
4. HH East canal shoals
5. Ditto – more shoaling
6. HH East Canal near junction of Plantation Canal (Canal A)
7. Culvert (vegetated) draining Belle Ormond Circle Subdivision

# Area Map from MH trestle to Stanton Hall

Murray Hill to Belle Ormond – canals incl HH East and Store House (Ormond Oaks) Canals and Canal A (Plantation)



# Murray Hill Trestle at CN RR looking South – Can we clear the stones fallen in?



# Ditch on N side of CN RR east of trestle

**Now**




**Excavated Sep 2020**



# Ditch on N side of CN RR, E of trestle, shoaled




# Hill Heights East canal shoaled



# Hill Heights East canal shoaled


**Now**



**Excavated late 2020**



# HH East canal near Plantation canal



# Plantation Canal culvert at Belle Ormond Circle

