

SPW (MONTZ Intermediate Map
Station)

CERTIFICATE OF SUBSTANTIAL COMPLETION

DATE OF ISSUANCE April 8, 2005

OWNER St. Charles Parish
CONTRACTOR Fleming Construction Company, Inc.
Contract: Montz Lift Station - Evangeline Road
Project: Montz Lift Station - Evangeline Road

OWNER's Contract No. S030201 ENGINEER's Project No. 094-19-16

This Certificate of Substantial Completion applies to all Work under the Contract Documents or to the following specified parts thereof:

**RECORDED IN THE ST. CHARLES PARISH
CLERK OF COURT OFFICE**
ON May 5, 2005
AS ENTRY NO. 307169
IN MORTGAGE / CONVEYANCE BOOK
1076 FOLIO 537
NO. OWNER

To St. Charles Parish
Fleming Construction Company, Inc
CONTRACTOR

The Work to which this Certificate applies has been inspected by authorized representatives of OWNER, CONTRACTOR and ENGINEER, and that Work is hereby declared to be substantially complete in accordance with the Contract Documents on

April 8, 2005
DATE OF SUBSTANTIAL COMPLETION

A tentative list of items to be completed or corrected is attached hereto. This list may not be all-inclusive, and the failure to include an item in it does not alter the responsibility of CONTRACTOR to complete all the Work in accordance with the Contract Documents. The items in the tentative list shall be completed or corrected by CONTRACTOR within 45 days of the above date of Substantial Completion.

EJCDC No. 1910-8-D (1996 Edition)
Prepared by the Engineers' Joint Contract Documents Committee and endorsed by The Associated General Contractors of America and the Construction Specifications Institute.

The responsibilities between OWNER and CONTRACTOR for security, operation, safety, maintenance, insurance and warranties and guarantees shall be as follows:

OWNER: St. Charles Parish will assume insurance upon final payment. No warranties or guarantees will be assumed by St. Charles Parish until the two-year warranty/guarantee period has ended, in full accordance with Article 13.12 of Section 00700 of the Montz Lift Station – Evangeline Road Contract Documents.

CONTRACTOR: Contractor shall remain responsible for security of equipment and materials, safety, and maintenance during completion of punch list items. Contractor shall maintain all warranties and guarantees for a period of two-year after the substantial completion date, in full accordance with Article 13.12 of Section 00700 of the Montz Lift Station – Evangeline Road Contract Documents.


The following documents are attached to and made a part of this Certificate:

Substantial Completion Punch List for Montz Lift Station – Evangeline Road, Project S030201.

This certificate does not constitute an acceptance of Work not in accordance with the Contract Documents nor is it a release of CONTRACTOR's obligation to complete the Work in accordance with the Contract Documents.

Executed by ENGINEER on April 8, 2005
Date

HARTMAN ENGINEERING, INC.
ENGINEER

By: 
(Rolland A. Mura, P.E.)


CONTRACTOR accepts this Certificate of Substantial Completion on April 8, 2005
Date

Fleming Construction Company, Inc.
CONTRACTOR

By: 
(Name of person authorized to sign, title)

OWNER accepts this Certificate of Substantial Completion on 3/5/2005, 2005
Date

St. Charles Parish
OWNER

By: 
(Albert D. Laque, Parish President)

**SUBSTANTIAL COMPLETION PUNCH LIST
MONTZ LIFT STATION – EVANGELINE ROAD
MONTZ, LOUISIANA
ST. CHARLES PARISH
Project S030201**

The following list is attached to and made a part of the Certificate of Substantial Completion and is based on the Project walk-thru conducted on April 8, 2005.

1. Clean up project area and remove construction debris
2. Tie-in existing 4-inch sewer force main from Evangeline S/D to new Wet Well
3. Mark location of second 4-inch sewer force main tap
4. Fill and grade entire area for positive drainage to ditch and dress and limestone access road to station from Evangeline Road
5. Straighten natural gas pipeline vent – contact pipeline company
6. Seed area and stabilize ditch bank
7. Install stainless steel mesh screen on Wet Well vent pipe
8. Repair broken electrical ground at station service pole and tighten loose electrical ground at Control Panel